



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
June 16, 2006

Supervisor 10271

Mine Name: Levan Henry
Operator Name: Sunroc Corporation
Tony Christofferson
525 W. Arrowhead Trail
PO Box 488
Spanish Fork, UT 84639
Inspector(s): Tom Munson
Other Participants: None
Mine Status: inactive

Permit number: M0230023
Inspection Date: 5/16/2006
Time: 1:18PM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To perform an inspection to see if the mine is active.

Directions to Site:

South of Nephi.

Inspection Summary:

The site was gated and I walked into the site and noticed the sediment pond had water in it. The rest of the site had no equipment on it. Most of the stock pile was removed and the site was completely inactive.

Conclusions and Recommendations:

Continue to watch the site from a maintenance standpoint and finish the permitting of the Large Mine permit.

Inspector's Signature Thomas Munson

Date: 6/19/06



Tm:pb

cc: Tony Chrisofferson
US Forest Service, Tom Shore, Ephraim


Attachment: Photos

O:\M023-Juab\M0230023-Henry 1&2\inspections\insp-5162006.doc


SINROC ATENRY 1-2



SUNROC HENRY 1-2




SUNROC HENRY 1-2



05.16.2006 13:09



05.16.2006 13:09



05.16.2006 13:09

SUNROC



HENRY 1-2

